

MOM Between Mys Bannari amman Sugars Ltd. Erode and Mys Voltamp & P. Ltd. on dtd 7/6/04 at BASL plant.

Mys Voltamp Representative Visited Site on 6/6/04 on Complaint of transformer JN 8028, 25 MVA 110/11KV YNd1, carried out the following activities.

Transformer tested at Low Voltage. Enclosed the Test Report. Test Report indicates Transformer is faulty. at 'W' phase (B phase)

Oil drained of about 8000 litres. Inspected the 'W' phase winding found burnt at Lead entry of HV. winding also got disturbed.

Had discussions with Mys Voltamp Baroda. and decided to send the Transformer to Baroda for repair.

Voltamp Representative Mr Shantharaj left the Site on dtd 7/6/04

Mys BASL arranging to Loading & transporting, dismantling, and asking Mys Voltamp to send representative to supervise the same. Mys BASL will intimate to Mys Voltamp within two days.

For Mys Voltamp
Shantharaj

Shantharaj N.R

For Mys BASL

P Dharmajan

BANNARI AMMAN SUGARS LIMITED

From

To

VICE PRESIDENT
SATHYAMANGALAM

GENERAL MANAGER (FINANCE)
COIMBATORE

RSL/22/ *P361* /200304

07/06/2004

Sub: Accident report for 25-MVA Transformer failed - covered under MBD policy - Reg
We are furnishing below the accident report for the 25-MVA Transformer for insurance
claims.

Sl. Name plate details No. of the transformer	Date and time of accident	Reason for failure	Location
01 25-MVA Generator Transformer Rating: 110-KV/11-KV-Ratio YN01-connection Impedance-10.34 Voltage Sl.No. JN8028/1 Make: VOLTAMP TRANSFORMERS LTD, BARODA	03.06.2004 3-5-51PM 5-51PM	R-phase winding insulation failure due to heavy lightning stroke in the transformer	Cogen division -Switchyard

The copy of minutes of meeting held with the engineer of M/s Voltamp is enclosed herein for
your further action.

P. Shanmugam
VICE PRESIDENT

Encl: Copy of log sheet
Copy of minutes of meeting

cc: O&M-Purchase

SK